

### RWP Technical Resolution Committee and Bulletins

Item	TRC Item	Old TB # (Status)	New TB #	Items Resolved	Items Not Resolved	Topic
1	N/A	N/A	G0501	N/A	N/A	Intro TB
2	9901	9901	G0502	1		Exclusive track occupancy, generally
3	9902	9902	G0503	5		Lone worker, generally
4	9903	9903	G0504	1		OTS training for T&E employees
5	9904	9904	G0505	1		Good faith challenge
6	9905	9905	G0506	1		Identifiable location for exclusive occupancy
7	9905	9906	G0507	3		Roadway worker in charge
8	9907	9907	G0508	1		Audible warning from train for work over large area
9	9908	9908	G0509	1		Plant trackage and on-track safety for railroad employees
10	9909	9909	G0510	1		Train approach warning and place of safety
11	9910	Not issued	N/A		1	Passenger platforms and snow removal
12	9911	Not issued	N/A		1	Tunnel niches

RWP Technical Resolution Committee and Bulletins

Item	TRC Item	Old TB # (Status)	New TB #	Items Resolved	Items Not Resolved	Topic
13	9912	Not issued	N/A		1	Block register territory
14	0401	(RCC not supportable)	N/A		2	Foul time
15	0402	(RCC not supportable)	N/A		1	Occupancy behind trains
16	0403	(Supportable with legal analysis)	G0511	1		Dual power switch locations and individual train detection
17	0404	(Supportable with legal analysis)	G0512	2		On-track safety documentation
18	0405	(RCC supportable)	G0513	1		On-track safety while establishing working limits
19	0406	(RCC supportable)	G0514	1		Operation of certain equipment on non controlled track
20	0407	(RCC not supportable)	N/A		1	Obstructing track under train approach warning
21	0408	(RCC supportable)	G0515	1		Audible warning from train and duration

### RWP Technical Resolution Committee and Bulletins

Item	TRC Item	Old TB # (Status)	New TB #	Items Resolved	Items Not Resolved	Topic
22	0409	(RCC supportable)	G0516	1		Annual training and periodic qualification
23	0410	(RCC supportable)	G0517	1		Roadway worker in charge and multiple groups
24	0411	(RCC supportable)	G0518	1		Other than roadway workers providing on-track safety
25	0412	(RCC supportable)	G0519	1		Maintenance of way contractor training
26	0413 (1.1)	(Supportable with legal analysis)	G0520	1		Effective securing device/other instruments
27	0414 (1.2)	(RCC not supportable)	N/A		2	Inaccessible track – train crew flagging & RMM encroachment
28	0415 (1.3)	(RCC supportable)	G0521	1		Other than maintenance of way crafts performing duties
29	0416 (1.4)	(RCC not supportable)	N/A		1	Speed restrictions and train approach warning/individual detection

RWP Technical Resolution Committee and Bulletins

Item	TRC Item	Old TB # (Status)	New TB #	Items Resolved	Items Not Resolved	Topic
30	0417 (2.1)	(RCC supportable)	G0522	1		Exclusive track occupancy and emergencies
31	0418 (2.2)	(RCC supportable)	G0523	1		Retention of exclusive occupancy records by dispatcher
32	0419 (2.3)	(RCC not supportable)	N/A		2	Securing unoccupied equipment within inaccessible limits
33	0420 (2.4)	(Supportable with legal analysis)	G0524	1		Adjacent tracks and small unit of major work
34	0421 (3.1)	(RCC supportable)	G0525	1		Revisions to on-track safety procedures and field manual
35	0422 (3.2)	(RCC not supportable)	N/A		1	Record of basic training
36	0423 (3.3)	(RCC supportable)	G0526	1		Shoving moves and whistle sounding
37	0424 (3.4)	(Supportable with legal analysis)	G0527	1		Whistle sounding and “on or about the track”

RWP Technical Resolution Committee and Bulletins

Item	TRC Item	Old TB # (Status)	New TB #	Items Resolved	Items Not Resolved	Topic
38	0425 (4.1)	(Supportable with legal analysis)	G0528	1		Portable radios and train approach warning
39	0426 (4.2)	(RCC supportable)	G0529	2		Controlled points vs. manual interlockings
40	0427 (4.3)	(RCC not supportable)	N/A		1	Watchmen standing in tracks
41	0428 (4.4)	(RCC supportable)	G0530	1		“Quiet” power tools
			30 TB's	37	14	